



Subject : Possible Governors, Feathering Pumps and Oil Distributors for AVIA Propellers

PROPELLER SERIES		GOVERNOR	FEATHERING PUMP	OIL DISTRIBUTOR
AV-723-()	Hydraulic variable pitch propeller	Avia Propeller P-8()-() MT-Propeller P-4()-() Woodward () 210 () () () () 8210 () () ()	N/A	N/A
AV-725-()	Hydraulic variable pitch propeller	Avia Propeller P-W2()-() Jihostroj LUN 7816.()	Avia Propeller AFP-28-() Praga Hostivar LUN 7840	N/A
AV-803-()	Hydraulic variable pitch propeller	Avia Propeller P-8()-() P-W2()-() MT-Propeller P-4()-() Woodward () 210 () () () () 8210 () () () Jihostroj LUN 7815.() LUN 7816.()	Avia Propeller AFP-28-() Praga Hostivar LUN 7840	N/A



This Service Bulletin was issued according the procedures established for the EASA certified design organisation No. EASA.21J.072.

Office of Airworthiness Zbyněk Tvrdlík Date : July 12, 2011		Issue Michal Rout Date : July 12, 2011		Page : 1 Pages : 4
---	---	--	--	-----------------------

**SERVICE BULLETIN
 No. 3G**



PROPELLER SERIES		GOVERNOR	FEATHERING PUMP	OIL DISTRIBUTOR
AV-842-()	Hydraulic variable pitch propeller	Avia Propeller P-8()()-() MT-Propeller P-4()()-() Woodward () 210 ()()() () 8210 ()()()	N/A	N/A
AV-843-()	Hydraulic variable pitch propeller	Avia Propeller P-8()()-() MT-Propeller P-4()()-() Woodward () 210 ()()() () 8210 ()()()	N/A	N/A
AV-844-1-B-() AV-844-1-D-()	Hydraulic variable pitch propeller	Avia Propeller P-8()()-() MT-Propeller P-4()()-() Woodward () 210 ()()() () 8210 ()()()	N/A	N/A

This Service Bulletin was issued according the procedures established for the EASA certified design organisation No. EASA.21J.072.

Office of Airworthiness Zbyněk Tvrđík Date : July 12, 2011 	Issue Michal Rout Date : July 12, 2011 		Page : 2 Pages : 4
---	--	--	-----------------------

PROPELLER SERIES		GOVERNOR	FEATHERING PUMP	OIL DISTRIBUTOR
AV-844-1-E-()	Hydraulic variable pitch propeller	Avia Propeller P-W2()-() Jihostroj LUN 7815.() LUN 7816.() LUN 7817.()	Avia Propeller AFP-28-() Praga Hostivar LUN 7840	N/A
V210	Fixed pitch propeller	N/A	N/A	N/A
V310	Ground adjustable pitch propeller	N/A	N/A	N/A
V410()	Electric pitch control propeller	Avia Propeller LUN 7800	N/A	N/A
V500()	Hydraulic variable pitch propeller	Praga Hostivar LUN 7810.01	N/A	Avia Propeller LUN 7902 P7900.01
V503()	Automatic hydraulic propeller	N/A	N/A	N/A
V506	Hydraulic variable pitch propeller	Praga Hostivar LUN 7810	Avia Propeller AFP-28-() Praga Hostivar LUN 7841	Avia Propeller LUN 7902-1 P7900 V506-6 V506-6.1
V508()	Hydraulic variable pitch propeller	Avia Propeller P-W2()-() Jihostroj LUN 7815.() LUN 7816.()	Avia Propeller AFP-28-() Praga Hostivar LUN 7840	N/A



This Service Bulletin was issued according the procedures established for the EASA certified design organisation No. EASA.21J.072.

Office of Airworthiness Zbyněk Tvrđík Date : July 12, 2011 	Issue Michal Rout Date : July 12, 2011 	Page : 3 Pages : 4
---	--	-----------------------

**SERVICE BULLETIN
 No. 3G**

PROPELLER SERIES		GOVERNOR	FEATHERING PUMP	OIL DISTRIBUTOR
V510()	Hydraulic variable pitch propeller	Avia Propeller P-W2()-() Jihostroj LUN 7816.()	Avia Propeller AFP-28-() Praga Hostivar LUN 7840	N/A
V520	Hydraulic variable pitch propeller	Praga Hostivar LUN 7811 LUN 7811.01	N/A	N/A

This Service Bulletin was issued according the procedures established for the EASA certified design organisation No. EASA.21J.072.

Office of Airworthiness Zbyněk Tvrđík Date : July 12, 2011		Issue Michal Rout Date : July 12, 2011		Page : 4 Pages : 4
--	---	--	--	-----------------------