

AVIA PROPELLER Ltd Beranových 65/666 199 00 Praha 9 Czech Republic	<b>SERVICE LETTER SL-3</b>	DOA No.  EASA.21J.072
---	--------------------------------	-----------------------------

**SUBJECT : Service Bulletins - Notice of Cancellation**



Avia Propeller Ltd. announces the cancellation of following Service Bulletins with summary of Product manuals of all propellers manufactured by Avia Propeller :

**V210/2b-R1 , V310/2b-R1 , V410/14b-R1 , V500A/10b-R1 , V503/8b-R1 , V503A/10b-R1 , V503AP/1b-R1 , V506/11b-R1 , V508/5b-R1 , V508B/9b-R1 , V508D/9b-R1 , V508D-2/3b , V508D-AG/3b-R1 , V508E/3b , V508E-AG/3b , V508Z/5b-R1 , V510/10b-R1 , V510T/3b-R1 , V510AG/4b-R1 , V520/8b-R1 , AV-723/1b.**

Summary of all product manuals (latest revisions) is presently dispoible on the Avia Propeller website [www.aviapropeller.com](http://www.aviapropeller.com), section Product Manuals.

**NOTE:**

Russian versions of all product manuals are not updated and they are replaced by appropriate english versions.

Office of Airworthiness Zbyněk Tvrdek  Date : February 23, 2007	Issue Michal Rout  Date : February 23, 2007		Page : 1  Pages : 1
--	--	--	---------------------------